

## Driller Report Summary

[Back](#)

### WELL NUMBER

Well Number	20211177
Driller Tag Number	D0121079
Date Received	06/11/2021

### WELL CONTRACTOR

License Code	982
Driller Name	RODNEY D TATUM
Rig Operator	SHAWN FOXX

### WELL LOCATION

County Name	MCNAIRY
Driller Map No.	3DW
Quad Name	PURDY
Quad Number	0004NE
Quad Nth	2
Latitude	35.23444444
Longitude	-88.55694444
Address	635 MANCLE MURRAY RD
Address Line 2	-
City Name	BETHEL SPRINGS
State Name	Tennessee
Zip	38325
Zip Ext	-
Distance From Landmark (miles)	6
Direction From Landmark	N
Nearest Landmark	Selmer

### TYPE OF WORK

Date Drill Rig Left Site	04/30/2021
Type of Work	New Well

### WELL COMPLETION DATA

Completion Date	04/30/2021
Total Depth (ft-bgs)	40
Depth To Bedrock (ft)	-

### WELL OWNER INFORMATION

Company Name	-
Owner Name	DAVE RUBEY
Address	635 MANCLE MURRAY RD
Address (Line 2)	-
City	BETHEL SPRINGS
State	Tennessee
Zip Code	38315
Phone	(701) 640-6888

### PROPOSED USE OF WELL

Well Use	Residential
----------	-------------

### PRIMARY CASING

Diameter (in)	4
Top Set (in-above ground)	6
Primary Casing Depth (ft-bgs)	20
Primary Casing Type	Plastic
Wall Thickness	40
SDR#	-

### WELL FINISH

Well Finish	Screen
From (ft-bgs)	20
To (ft-bgs)	40
Screen Type	Plastic
Slot Size (in)	0.02
Gravel Pack From (ft-bgs)	20
Gravel Pack To (ft-bgs)	40

### BACK FILL MATERIAL

Back Fill Type ↑≡	From (ft-bgs)	To (ft-bgs)
Bentonite	3	10
Cuttings	10	20

### LINER CASING

Static Level (ft-bgs) 15

Estimated Yield (GPM) 25

WATER-BEARING ZONES

Depth (ft-bgs) ↑≡	GPM	GPH	Water Quality
15	25	-	good

WELL TEST

Tested By Pumping

Static Level (ft-bgs) 15

Pumping Level (ft-bgs) 35

Test After Hours 1

Test After Mins -

Test Yield (GPM) 25

Hours Prior to Test 1

Minutes Prior to Test -

FORMATION LOG

Depth from (ft) ↑≡	Depth to (ft)	Description
0	20	brown sand
20	40	light brown sand

COMMENTS

Comments -

Type None

Diameter (in) -

From (ft-bgs) -

To (ft-bgs) -

Packers Installed? N

Packer 1 Depth (ft-bgs) -

Packer 2 Depth (ft-bgs) -

ANTICIPATED WATER QUALITY

Appearance Clear

Taste Good

Odor -

Other -

GENERAL INFORMATION

Well Disinfected? Y

Well Capped? Y

50ft From Septic System? Y

Septic Distance Provided By Health Department Permit

Drilling Process Water Obtained From Public Supply

Pump Installed By Driller? Y

